

Case Study: Chatter Resolution in Cold Mill

R. Evans
April 2013

29/04/2013



Overview

- **History**
- **Analysis methods**
- **Resolution**
- **Benefit to client**




Problem History

- **Problem existed on mill for 5 yrs prior to RE involvement**
 - Plant disqualified from various customers for sheet defects only visible upon secondary forming operations
 - New products ran at slower speed to avoid defects
- **Problem resurfaced after an emergency motor bearing replacement**
 - Speed limited to 600 m/min (max speed 1300 m/min)
- **Plant requested help from**
 - FAG bearing manufacturer/SMS mill builder/Universities
 - Problem not resolved



Problem Overview

- **At speeds > 600 m/min transverse lines visible across sheet**
- **Spacing approximately 22 mm**
- **Not visible at speed < 600 m/min**




Problem Evaluation

- **Evaluation of resonant frequencies of mill**
- **Carried out analysis of typical contributors to forced vibration**
- **Evaluated condition of various mill components**
 - Bearings
 - Hydraulics
 - Couplings
- **Evaluated roll grind shop**
- **Assessed plant capability to detect problem**
 - Using plant-based equipment



Problem Data Analysis

- **Not resonance issue**
 - Defect is visible in accelerometer measurements at all speeds
- **Evaluation of hydraulics/couplings showed no issues**
 - Calculated frequencies did not match visible defect
- **Calculated frequencies closely matched bearing defect in BUR**
 - Not exact match




Top Back-up - OS

22 mm markings

Data Analysis

- **Proved defect present at all speeds**
 - Not visible to naked eye below 600 m/min but still present (plant equipment)




42.69/m = 22mm defect spacing



Problem Data Analysis

- Evaluation of roll grinders showed rolls were being ground with defects
- Evaluation of roll surfaces (plant equipment) demonstrated that surface was marked
 - Origin found to be bearing journals on roll necks



Problem Resolution

- **Ran trial with new BURs and bearings**
 - No defects at any speed
 - Combinations of new/old BURs and bearings
 - Defects visible both old BUR/new bearings & new BUR/old bearings
 - Suggested bearing upgrades to allow full speed with all rolls
 - Suggested maintenance/upgrades to grinders to eliminate “ground-in” defect
- **Developed online monitoring system for detection of defect at all times**
 - iba based system tied directly to plant data acquisition



Benefit to Client

- **Problem source uncovered**
- **Immediate steps for resolution recommended**
- **Ongoing maintenance SOP developed**
- **Online detection system eliminates customer complaints**
- **Demonstrated that speed increase to mill max was possible after recommendations carried out.**

